



Technical Information Bulletin

Date 4/6/2005

04221A s/n: D31375 – D31394

Symptom:

Bolt installed on leading edge of die, preventing it from being inserted in OD4000/OD4800 punch.

Solution:

Remove and discard bolt and washer. Bolt and washer were inadvertently install and should not have been for this model of punching die.



Performance Design 2350 E. Braniff St. Boise, ID. 83716
Phone: 1-800-390-5782 Fax: 1-800-390-5783
Hours: 8:00 AM-5:00 PM Mountain Standard Time