



Technical Information Bulletin

Date 1/8/2007

Model: HD7700 All machines up to S/N:G2838

Change direction of fan for better airflow

Problem:

Excessive heat on Brake & Motor

Solution:

Instructions: Turn power switch off and disconnect power cord and foot-pedal from machine. Remove 8 phillips head screws securing back panel of machine. Remove four nyloc nuts from backside of fan. Remove four phillips head screws from fan. Install fan so that airflow is from outside of machine to inside of machine. Reinstall long phillips screws for fan and tighten nyloc nuts until they just contact fan body. Reinstall 8 phillips heads screws for back panel.



Correct Direction



Performance Design 2350 E. Braniff St. Boise, ID. 83716
Phone: 1-800-390-5782 Fax: 1-800-390-5783
Hours: 8:00 AM-5:00 PM Mountain Standard Time