



Technical Information Bulletin

Date 2/2/2004

RAF-11 s/n: L1029 and lower, including serial numbers without “L” designator.

Symptom:

As paper is being drawn down from the pile and into the punching die, it is skewed to the left or the right causing a paper jam or incorrect punching of the paper.

Solution:

Contact Performance Design for a list of replacement parts to revise the machine. Parts will include a new left and right paper pile side guides, paper pads and roller plate pads.

